

工事後モニタリング(メタンガス・硫化水素)測定日前1週間の晴雨状況表 (R2. 9. 30現在)

天気記号凡例: ☀️ 快晴又は晴れ、☁️ 曇り、☔️ 雨(時々、一時、にわかを含む)、❄️ 雪(霰、霰を含む)、🌀 台風、☔️ 降雨又は降雪あり
 記号が**大**(時間的に長い場合)・**小**(時間的に短い場合) 基本的に**粕屋町の天候**(ただし、休み等の場合は近隣福岡市博多区周辺の場合あり)、当日の天気:上段漢字は業者の表示 下段天気記号は町の表示
気温: 福岡地区における**上段が最高気温**、**下段が最低気温**

工事後モニタリング(メタンガス・硫化水素)測定日前1週間の晴雨状況																																								
西暦	2017年						2018年						2019年						2020年				2021年				2022年	2023年												
測定月日 天気	7/25	8/22	9/21	10/17	11/17	12/15	1/19	2/16	3/20	4/18	5/15	6/1	7/2	8/3	9/14	10/11	11/8	12/14	1/18	2/15	3/1	4/15	5/15	6/12	9/9	12/4	3/2	6/10	9/10	12/	3/	6/	9/	12/	3/	6/	9/	12/	3/	
最高	35.9	34.8	27.2	20.9	14.1	12.5	13.1	10.3	10.4	20.7	30.5	25.3	31.8	34.6	29.2	18.7	23.5	10.4	12.6	16.1	17.0	18.0	29.9	25.4	34.8	14.1	14.8	32.7	31.6											
最低	27.5	26.2	21.6	16.4	7.0	3.4	6.6	3.7	9.6	10.0	17.2	17.8	26.8	27.7	24.7	17.3	16.9	7.4	3.8	4.1	6.9	10.0	18.3	18.7	25.9	6.9	9.8	23.1	22.5											
前日	☔️	☔️	☁️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️											
最高	32.3	32.7	28.7	18.2	14.8	9.4	12.9	10.4	17.6	16.3	26.3	24.6	35.2	37.5	30.5	23.4	23.5	10.2	8.8	13.5	15.2	18.8	28.9	25.8	34.2	10.1	12.4	33.8	29.2											
最低	28.4	26.6	22.9	16.5	10.8	3.1	6.9	8.8	14.3	14.4	15.8	22.2	23.8	27.9	23.1	20.8	12.3	4.9	2.5	10.1	8.5	12.2	20.1	18.4	25.8	8.3	7.4	22.1	21.8											
2日前	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️											
最高	34.6	34.2	28.9	17.8	16.1	7.3	13.3	14.3	19.0	20.3	21.2	29.9	27.7	34.9	28.7	25.4	22.5	12.0	8.8	18.9	12.8	19.2	26.4	25.9	30.8	14.7	10.6	30.6	32.8											
最低	27.9	25.9	19.7	16.6	12.6	2.1	11.5	0.7	7.8	10.3	20.9	22.0	21.6	27.9	23.7	17.8	11.6	9.5	5.8	7.1	8.0	8.0	17.2	19.5	28.8	12.7	7.1	18.4	24.1											
3日前	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️											
最高	35.5	32.6	29.5	22.3	20.4	4.7	18.6	6.9	15.1	17.4	27.1	27.6	27.9	33.7	28.6	26.4	22.0	9.8	11.0	12.5	16.5	17.3	26.6	25.9	34.8	19.6	11.6	25.9	29.8											
最低	28.3	25.5	21.7	18.8	14.8	3.1	4.4	2.1	4.6	12.4	16.7	20.3	23.0	27.7	19.9	19.2	10.6	4.7	6.7	4.4	6.8	9.8	17.7	18.6	25.8	9.9	4.3	20.6	25.6											
4日前	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️											
最高	35.5	32.6	24.1	21.3	19.4	9.1	9.2	5.2	9.8	23.1	25.3	25.1	30.5	32.3	27.2	27.4	21.4	11.1	14.1	8.1	15.4	14.8	25.9	25.0	33.2	16.8	12.1	24.7	27.5											
最低	26.8	24.7	21.9	18.5	9.3	7.7	1.5	0.5	9.1	17.1	11.3	20.6	27.9	25.0	20.7	21.9	11.9	4.0	5.6	5.2	6.0	11.0	15.9	18.6	25.1	6.4	8.5	21.3	24.8											
5日前	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️											
最高	32.9	34.8	23.7	26.1	19.3	11.1	7.9	5.8	19.9	24.1	20.6	29.3	31.7	29.8	25.5	28.1	21.0	8.1	13.2	9.0	14.4	14.4	26.3	30.9	31.2	15.4	16.5	30.3	28.9											
最低	25.9	25.2	20.9	22.9	10.6	7.4	1.1	2.3	13.8	13.0	10.4	17.4	27.8	26.9	20.8	24.6	9.6	4.7	9.7	8.6	6.5	12.6	13.8	21.2	24.5	7.1	12.0	21.4	23.6											
6日前	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️											
最高	32.6	32.9	24.1	28.9	16.9	9.5	5.5	8.9	23.0	23.0	19.0	27.2	31.7	34.1	22.5	30.2	19.7	7.7	13.3	14.1	15.0	21.0	23.6	30.2	31.9	14.5	19.7	28.8	31.2											
最低	26.0	25.1	20.8	20.5	14.6	4.1	0.3	7.0	11.3	13.3	14.4	19.4	22.9	27.2	21.6	19.8	9.7	4.4	6.8	3.8	10.1	11.0	15.1	22.4	23.2	11.6	11.5	21.1	24.8											
7日前	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️	☔️											
最高	34.1	31.5	27.4	29.0	22.8	7.9	3.8	14.6	21.8	24.4	17.6	29.0	30.7	34.6	29.5	23.3	18.9	12.0	11.9	12.9	12.9	20.7	22.8	31.1	29.2	16.2	17.4	26.4	33.4											
最低	28.3	26.0	22.2	20.4	12.3	6.9	0.4	0.9	8.4	18.9	16.2	18.9	21.3	28.0	25.1	17.4	10.6	11.5	5.8	2.9	8.0	13.6	10.1	22.1	23.0	12.1	4.8	20.4	25.8											

2017. 7月~2019. 6月(工事後2年間)

2019. 7月~2020. 6月
(工事後3年目)

2020. 7月~2021. 6月
(工事後4年目)

2021. 7月~2022. 6月
(工事後5年目)

工事了(2017. 6月末)